M400004

Hard Hat Tether

⚠ **WARNING:** Active dropped object prevention equipment must only be used as it was designed. Users must read and understand all safety information within the user instructions provided with the product. Before using an active dropped object system, users must be trained on the installation and safe use of the system. Misuse or failure to heed these warnings and instructions may result in injury or even death.

WORK SAFE! WORK SMART!

Important
Before use, the user must read and understand these User Instructions. Keep these User Instructions for reference.

Purpose
M400004 Hard Hat Tether is designed to prevent the hazards associated with dropped objects when working at height. Use only as part of an active dropped object prevention system.

Use Instructions
1. Before using an active dropped object system, employees must be trained on the installation and safe use of the system and its components.
2. Active dropped object systems, including the M400004 Hard Hat Tether, must be inspected prior to each use for wear, damage, and other deterioration. Defective components must be immediately removed from service.

Installation
M400004 Hard Hat Tether is to be installed on the hard hat utilizing the accessory slot.

1. Pass the end of the M400004 Hard Hat Tether through the accessory slot on the hard hat.
2. Then pass the end through the clamp and close the clamp. Check to make sure the connection is secure.
3. Wrap the buckle end of the M400004 Hard Hat Teather around the shoulder strap of the full body harness and connect the buckle. Check to make sure the connection is secure.

Inspection
All M400004 Hard Hat Tethers must be inspected prior to each use. Local, state, governmental and jurisdictional agencies governing occupational safety may require the user to conduct more frequent or mandatory inspections.

All webbing must be inspected for tears, cuts, fraying, abrasion, discoloration, burns, holes, mold, or other signs of wear and damage.


All Hard Hat Tethers must be free of corrosion, chemical attack, alteration, excessive heating or wear.

Hard Hat Tether must clamp firmly on itself to secure hard hat.


If inspection reveals any defect, or unsafe condition, remove from service and replace.

Note: Only Werner Co., or persons or entities authorized in writing by Werner Co., may make repairs or alterations to the equipment.


Step 1




Step 2



Step 3





User Instruction Manual

WERNER CO. CORPORATE HEADQUARTERS: 93 Werner Rd., Greenville, PA 16125-9499
TEL: 888-523-3370 FAX: (724) 588-0315 www.wernerco.com

117774-01 ©2018 Werner Co. Rev A 08/18