

CAUTION- WHEN LOADING - MOVE FORKS UNDER PALLET AND PUSH HANDLE FORWARD AGAINST LOAD UNTIL WHEELS LEAVE FLOOR AND FORK LOCK "CLICKS" INTO POSITION WITH FRAME AT RIGHT ANGLE TO FORKS - THEN PULL LOAD BACK ONTO WHEELS.

CAUTION- WHEN UNLOADING - PUSH HANDLE FORWARD AGAINST LOAD UNTIL SLIGHT PRESSURE ON FOOT PEDAL RELEASES FORK LOCK - DO NOT APPLY EXCESSIVE PRESSURE ON FOOT PEDAL.

Z40470A6