



# Certificate of Compliance

**Certificate:** 1777298

**Master Contract:** 234350

**Project:** 80122991

**Date Issued:** 2022-6-20

**Issued To:** Shanghai Yili Electric Co., Ltd.  
Building 2, No. 1318  
Xiangyang Road  
Minhang District, Shanghai, 201108  
China

**Attention:** Chen Hongyan

*The products listed below are eligible to bear the CSA Mark shown with adjacent indicators 'C' and 'US' for Canada and US or with adjacent indicator 'US' for US only or without either indicator for Canada only.*



**Issued by:** Yuehui (Tina) Zhang  
Yuehui (Tina) Zhang

## **PRODUCTS**

CLASS - C161103 - CLEANING MACHINES Cleaning machines (floor)

CLASS - C161183 - CLEANING MACHINES High Pressure Cleaners

High pressure washer, cord connected, double insulated. Models ML4560C-140B, ML3380-100B, PW162500AV, PW182500AV, PW183500AV, SPX1500, SPX1501, SPX1501(SJG), SPX1501(SJB), SPX1501(RED), SPX1501(GRY), SPX2500, SPX3000, SPX2598, YLQ5450C-140A, SPX3001, SPX4000, SPX4001, SPX4003, YLQ07S-100, YLQ16S-130, YLQ17S-130, YLQ22S-150, YLQ22SH-150, YLQ27SC-130, YLQ4391C-100, YLQ4480C-100B, YLQ4640C-120, YLQ5.32SC-140, YLQ5321C-120, YLQ5640C-130A, YLQ5660C-140B, YLQ6.33SC-140A, YLQ6.33SC-140B, YLQ6380C-140B, PW20, YLQ5451C, SPX200E, YLQ3720-90, PW21, YLQ6660C-140B; SPX202E, MTS-1300PW-MPL, MTS-1300PW-MBR, MTS-1300PW-MGN, MTS-1300PW-MBK, YLQ4740C-100; SPX3200, YLQ5660C-120B, 239161801, SPX2600, SPX2600-SJG, SPX2600-RED, YLQ3722-90, SPX2598-MAX, YLQ5452-120A, SPX2003, SPX2599-MAX, SPX4004-MAX, SPX205E, SPX206E, SPX2598-ELT, SPX4003-ELT, SPX2002-MAX, SPX3000-XT1, SPX3000-XT, SPX2004, SPX4003-ULT, SPX2597-MAX, SPX205E-MAX, SPX2005P, YLQ5740C-140, 8976979,



**Certificate:** 1777298  
**Project:** 80122991

**Master Contract:** 234350  
**Date Issued:** 2022-6-20

---

YLQ4720C-100, 8976904, SPX3550, SPX3220, SPX2688-MAX, SPX2700-MAX, SPX3160, SPX3000-PK1, SPX2596-XXX, SPX2680-MAX, YLQ4500H-140C, SPX2690-MAX, YLQ5500H-140A, YLQ6.33H-160A, SPX3000-SJG, SPX3000-SJB, SPX3000- BLK, SPX3000- RED.

**Note:**

For details related to rating, size, configuration, etc. reference should be made to the CSA Certification Record or the descriptive report.

**APPLICABLE REQUIREMENTS**

CSA-C22.2 No.68-18 - Motor-Operated Appliances (Household and Commercial)  
UL 1776-3rd Edition - High-Pressure Cleaning Machines

**Notes:**

---

Products certified under Class C161103, C161183 have been certified under CSA's ISO/IEC 17065 accreditation with the Standards Council of Canada (SCC). [www.scc.ca](http://www.scc.ca)





## Supplement to Certificate of Compliance

Certificate: 1777298

Master Contract: 234350

*The products listed, including the latest revision described below, are eligible to be marked in accordance with the referenced Certificate.*

### Product Certification History

Project	Date	Description
80122991	2022-6-20	Update Report 1777298 to add alternate motor item 18J and pump item 3D to models SPX3000, SPX3000-PK1. Add new models YLQ6.33H-160A, SPX3000-SJG, SPX3000-SJB, SPX3000- BLK, SPX3000- RED.
80122990	2022-5-30	Update Report 1777298 to add new models SPX2680-MAX, YLQ4500H-140C, SPX2690-MAX, YLQ5500H-140A.
80105803	2021-11-30	Update Report 1777298 to add new model SPX2596-XXX.
80093479	2021-08-11	Update report 1777298 to add alternate switch box for models SPX2599-MAX, SPX2700-MAX, SPX2598, SPX2597-MAX, SPX2598-MAX, SPX2598-ELT, SPX2688-MAX, YLQ5452-120A, YLQ5450C-140A and add new GFCI for all models.
80080604	2021-06-16	Update Report 1777298 to add new models SPX3550, SPX3220, SPX2688-MAX, SPX2700-MAX, SPX3160, SPX3000-PK1.
80066319	2021-01-29	Update Report 1777298 to add new models YLQ4720C-100, 8976904, YLQ5740C-140, 8976979. Modify motors' manufacturer name and shaft insulation material. Add alternate armature slot liner on motor item 18D. Correct brush dimension and stator winding turns on motor item 18D.
80062609	2020-11-23	Update report 1777298 to add new models SPX2004, SPX4003-ULT, SPX2597-MAX, SPX205E-MAX, SPX2005P, add new optional low-pressure accessories.
80039662	2020-05-08	High Pressure washer, Update Report 1777298 to add new models SPX3000-XT1, SPX3000-XT.
80031251	2020-03-17	Update Report 1777298 to add new model YLQ4640C-120.
80029021	2020-01-16	Update report 1777298 to add new model with same enclosure as certified model. Update standard to CSA C22.2 No 68-18
80029155	2020-01-15	Update report 1777298 to add new models SPX2598-ELT, SPX4003-ELT.



80017011	2019-11-12	Update report 1777298 to add new models SPX2003
80001527	2019-05-21	Update report 1777298 to add new model SPX2598-MAX.
70214442	2019-04-11	Update report 1777298 to add new model SPX2600.
70203865	2019-01-08	Update report to include new model SPX4003.
70199943	2018-11-23	Update report 1777298 to add new model YLQ5660C-120B.
70171154	2018-02-08	Update report 1777298 to add new model YLQ5450C-140A, SPX2598. Same as certified model SPX3000/4000 except enclosure
70164833	2017-12-14	Update Report 1777298 to add new model SPX1501.
70132599	2017-09-22	Update report 1777298 to add new models PW21, YLQ6660C-140B; SPX202E, MTS-1300PW-MPL, MTS-1300PW-MBR, MTS-1300PW-MGN, MTS-1300PW-MBK, YLQ4740C-100; SPX3200
70113632	2017-03-27	Added new models SPX200E, YLQ3720-90.
70117427	2017-03-14	Update report 1777298 to add new models PW20, YLQ5451C.
70106373	2016-12-23	Added new models ML4560C-140B, YLQ5660C-140B, ML3380-100B, YLQ4480C-100B.
70094424	2016-11-10	Update report 1777298 to add new model SPX4000, SPX4001.
70076244	2016-04-27	Update report 1777298 to add new models SPX2500, YLQ5640C-130A, SPX1500, YLQ4640C-120.
70053638	2015-11-19	Added new model SPX3000.
70036013	2015-07-08	Add alternate UL and cUL Recognized GFCI and alternative switch models KCD4, DMC-1120, KD01, DMC-1220 and V15T22.
70022613	2015-03-16	Added models SPX3001, YLQ6380C-140B.
2585799	2013-01-07	Added models YLQ5321C-120, YLQ4391-100, YLQ6.33SC-140A.
2393384	2011-02-14	Added Models PW162500AV, PW182500AV, PW183500AV.
2338102	2010-09-30	Added Models YLQ27SC-130, YLQ5.32SC-140, YLQ6.33SC-140.
2282574	2010-03-17	Update to Report no.1777298 to add alternate spray wand
1895091	2007-04-27	Update to Report 1777298 to add new models YLQ22S-150 and YLQ22SH-150, which are the same as model YLQ16S-130 except Enclosure.



1862836	2006-12-14	Added alternate GFCI, Type 16592 by Leviton.
1828712	2006-10-17	Added alternate length of High-pressure hose for US Market.
1777298	2006-06-13	Original Certification.